This page lists the know errors on the gm5x5x5 PCBs. There are no known issues with the bulk order run (white pcbs), the following information is valid **only** for the prototype run (green pcbs).

## **Bulk Order #1 (white pcb, rev 1.0)**

## #1 Silkscreen error (reported by dioioib)

**Problem**: The silkscreen has the EEPROM the wrong way around - Pin 1 should be facing IC5.

**Solution**: Stick the EEPROM in the other way around, with the "notch" facing IC5.

# **Prototype Run (green PCBs)**


## #1 MIDI IO pins

**Problem**: The MIDI IO pins of the midi sockets (Pin 4 + 5) are switched.

**Solution**: Either (1) use the pin-headers if you use sockets that are not mounted on the pcb or (2) break the traces to pins 4 + 5 of the sockets and solder wires to them or (3) solder the midi sockets on the other side of the pcb.

#### **#2 MISSING TRACK**

Problem: A track between D2 and R3 is missing.



**Solution**: Bridge the pins.

From:

http://midibox.org/dokuwiki/ - MIDIbox

Permanent link:

http://midibox.org/dokuwiki/doku.php?id=gm5x5x5\_errata&rev=1265543070

Last update: 2010/02/07 11:44



http://midibox.org/dokuwiki/ Printed on 2025/11/14 12:14