To find midi devices known to cause problems check the midi_interface_blacklist.

Known to work MIDI interface/OS combinations include the following:

Vendor	Model	OSs	notes
Emagic	amt8	Mac OS X 10.5	
	Unitor8	Mac OS X 10.5	
E-MU	0404 USB	Windows XP, Windows 7	
	1616	Windows XP	
ESI	RoMI/O I		
M-AUDIO	FastTrack Ultra	Windows 7 64bit	
	MIDISport 2×2	Windows XP , Windows 7 64bit, Linux	Does not work with MIDI Thru toggled.
	UNO	Windows XP 32bit	
MBHP_USB_PIC		Windows XP, Windows Vista, Win7, MacOS 10.5, MacOS 10.6	
MIOS32 based USB devices		Windows XP, Windows Vista, Win7, MacOS 10.5, MacOS 10.6	
MOTU	FastLane USB	Windows XP, MacOS 10.4	
	midi express XT	Win7 64bit	
	UltraLite MKIII	MacOS 10.5, MacOS 10.6	
Novation	25SL mk2	Windows 7 64bit	
Phonic	FireFly 808	Win7	
Plyotec	gm5	Windows XP, Win7, MacOS 10.6, Linux	
Soundblaster	Audigy		Some older driver versions don't work reliable, use the latest one.
Steinberg	MIDEX3	Windows XP	
	MIDEX8	Windows XP	
Tascam	US-122L	Win7	
Terratec	MIDI Hubble 2×2	Win7	



When adding to this list, try to keep it sorted alphabetically, please.

From:
https://midibox.org/dokuwiki/ - **MIDIbox**

Permanent link:
https://midibox.org/dokuwiki/doku.php?id=midi_interface_whitelist&rev=1353387185

Last update: **2012/11/20 04:53**