

Problems with SysEx transfers have been noticed with following MIDI interfaces:

**Soundblaster Audigy:** some older driver versions don't work reliable, use the latest one

**Tascam US-122:** bytes get lost during SysEx transfer, even with the most recent windows driver version 3.3 **Tascam US-122L:** is OK!

**Yamaha UX256:** bytes get lost during SysEx transfer under WinXP and 2000 (earlier versions not tested), even with most recent MIDI drivers (Yamaha *universal* drivers)

**ESI MIDIMATE:** works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK.

**ESI Rom I/O II:** this device it's driver free, as the USB audio support in the OS automatically supports it (win & mac) but MIO Studio don't recognize the MIDI Ports of it. The device Rom I/O 1st release work fine instead, it come with own drivers.

**Behringer BCA2000:** works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. See the [Re: Impossible to upload MIO](#) thread for details.

**Behringer BCR2000:** works unreliable for SysEx transfers under OS X (10.5). Plain MIDI sending/receiving seems OK.

**M-Audio Keystation Pro 88:** works unreliable for SysEx transfers under Windows XP. Plain MIDI sending/receiving seems OK. See the [Re: Impossible to upload MIO](#) thread for details.

**CME VX 5:** works unreliable for SysEx transfers under OS X (10.5). Suspected SysEx filtering. Plain MIDI sending/receiving seems OK.

**Access Virus TI Polar:** works unreliable for SysEx transfers under OS X (10.5). Suspected SysEx filtering. Plain MIDI sending/receiving seems OK.

**SWISSONIC MIDI-USB 1x1** works unreliable for SysEx transfers under Windows (e.g. Buffer overrun messages during code upload)

From:

<http://midibox.org/dokuwiki/> - **MIDIbox**

Permanent link:

[http://midibox.org/dokuwiki/doku.php?id=midi\\_interface\\_blacklist&rev=1233258798](http://midibox.org/dokuwiki/doku.php?id=midi_interface_blacklist&rev=1233258798)



Last update: **2009/01/29 19:53**