

The process of calibrating a meter so that it shows a value of zero (0) when zero is being measured. This process must be done to insure accurate readings during the test session.

From:
<http://midibox.org/dokuwiki/> - **MIDIbox**



Permanent link:
<http://midibox.org/dokuwiki/doku.php?id=zeroing>

Last update: **2006/10/15 09:35**