


BS0, BS1 and BS2 at backside
of OLEDs have to be soldered to GND!!!

NOTE: The frontside of the LCD is shown here!
The display has to be flipped for soldering.



MBHP_CORE_STM32F4

MIDIbox Hardware Platform
MIOS32 SSD1306 --- Connection to ALIENTEK Module!
via Alternative Port
(must be supported by Application, e.g. MIDIbox CV V2)
(C) T. Klose 2014-01-27