

## BLM SCALAR FIX

Based on findbhudda's design: <http://www.midibox.org/dokuwiki/doku.php?id=findbuddha>

### DESIGN SOFTWARE USED:

---

Same as findbhudda :)

KiCAD for PCB/Schematics: [http://kicad.sourceforge.net/wiki/Main\\_Page](http://kicad.sourceforge.net/wiki/Main_Page)

### KNOWN ISSUES / BUILD SUGGESTIONS:

---

- blm-scalar.\* contain an error. Pins I4-I7 are mirrored. This is easily fixed with a connector modification, and the blm-scalar module seems to work as intended.
- blm-scalar v1.1 attempts to fix this error. Moved connectors J1, J2, Resistor Net 1 and R9 to make room for corrections.

### DESIGN FILES:

---

Original files from findbhudda [findbuddha-shared-wiki-docs-0.1.zip](#)

Corrected blm-scalar v1.1.brd [blm-scalar\\_v1.1..zip](#)

From:  
<http://midibox.org/dokuwiki/> - **MIDIbox**



Permanent link:  
<http://midibox.org/dokuwiki/doku.php?id=peterpressure&rev=1323631002>

Last update: **2011/12/11 19:16**